



Service History Certificate

Vehicle Registration Number - DU68WRD

VIN, Chassis Number - ***30**

Vehicle Description - Isuzu D-Max 1.9 Yukon Fury Double Cab Auto

Colour - Fury Red

Mileage - 19,980

Service History.

| Date of Service | Type of Service | Mileage | Dealer |
|------------------------|------------------------|----------------|---------------|
| 29/11/2019 | Inspection | 11,512 | Isuzu |

Please note: Vehicles are serviced in accordance to the manufacturer's schedule.

MOT Status.

The First MOT is Due 26/11/2021

Additional Information.

The above data is limited to the service work carried out by a member of the manufacturer's authorised network or other verified independent service centres.