

## Service history

Print Date 17/08/2021

Make: Mazda

Colour: BLUE

Registration: KP18 TTK

Model: CX-5 Sport (Nav) 2.2TD 5dr Station  
Wagon Manual

Agreement Start Date: 14/04/2018

VIN No.: JMZKF6W1600665593

Date	Odometer	Repairer	Reason	Action	Job Description	Job Breakdown
16/11/2018	13791	Rockingham Cars Mazda Corby	Routine	Routine	Manufacturer Service - Distance Based	Long Life Oil
			Routine	Routine	Manufacturer Service - Distance Based	SUMP PLUG WASHER
			Routine	Routine	Manufacturer Service - Distance Based	OIL FILTER
12/06/2019	27354	Rockingham Cars Mazda Corby	Routine	Routine	Manufacturer Service - Distance Based	POLLEN FILTER
			Routine	Routine	Manufacturer Service - Distance Based	SUMP PLUG WASHER
			Routine	Routine	Manufacturer Service - Distance Based	Brake/Clutch Fluid
			Routine	Routine	Manufacturer Service - Distance Based	OIL FILTER
			Routine	Routine	Manufacturer Service - Distance Based	Long Life Oil
			Worn	Remove & Refit (Replace)	Pads - front (Axle Set) (Brakes)	FRONT BRAKE PADS
09/03/2020	41050	Rockingham Cars Mazda Corby	Routine	Routine	37500 Miles Service (High)	OIL FILTER
			Routine	Routine	37500 Miles Service (High)	Long Life Oil
			Routine	Routine	37500 Miles Service (High)	FUEL FILTER
			Routine	Routine	37500 Miles Service (High)	SUMP PLUG WASHER
			Routine	Routine	37500 Miles Service (High)	AIR FILTER
03/09/2020	44370	Rockingham Cars Mazda Corby	Worn	Remove & Refit (Replace)	Door (front) - aperture seal/weatherstrip left outer	door seal
11/03/2021	51486	Donalds Mazda Peterborough	Routine	Routine	Other Unspecified Work - Routine, PPE costs	
			Routine	Routine	MOT test	
			Routine	Routine	50000 Miles Service (High) (50k)	fuel filter
			Routine	Routine	50000 Miles Service (High) (50k)	oil filter
			Routine	Routine	50000 Miles Service (High) (50k)	Synthetic Oil
			Routine	Routine	50000 Miles Service (High) (50k)	air filter
			Routine	Routine	50000 Miles Service (High) (50k)	brake fluid
			Routine	Routine	50000 Miles Service (High) (50k)	washer
Routine	Routine	MFL VCD Inspection (Vehicle Condition Document)				